

## **APPENDIX J**


## **Typical Building Elevations for**

## Phase 1









Left Side







Back







July 20, 2016 |



Shows the difference between the new windows (upper left three windows) and the original windows. (Building 11)



Photograph 2 Shows a building with new windows. (Building 23)



**Dover Greens** 

Dover, New York

Window Replacements Photographs